

## M7 Forward Repair System

SC: 4940-95-E41, 4940-95-E42  
NSN: 4940-01-463-7940  
LIN: F64544  
TM: 9-4940-568-10  
Related Documents: [RESET Program Checklist](#)

### System Description

The FRS is an 8' X 8' X 20' containerized tool shop.

### System Mission

Provide Organizational and Direct Support Level Maintenance and Repair of Combat Systems in the Forward Battle Area.

### Reset Type

**Reset Repair (National Level)** - Work performed to correct equipment faults that are above the ORG/DS level; performed by DOL, contractors, and Army's industrial base.

### Reset Strategy

Once a RESET candidate is identified, and the Inspection checklist has been completed, the item manager must be contacted to issue disposition instructions.

The FRS will be shipped direct to the RESET Location. Equipment brought to 10/20 condition. Including but not limited to: Replace tools, rubber air hoses, countertops, generator batteries, propylene gas components, steel hinges and eye wash bottles. Install 220V outlet and new air line shut off valve. Overhaul air compressor, crane and generator. Tear down to flat rack and inspect for cracks.

### Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.
- Reorder consumables IAW SC.
- Service SKO IAW TM to 10/20 (annual service) and LO.
- Service prime mover/trailer IAW platform guidance.
- Complete RESET Checklist and Verify with TACOM LAR or RLNO.

### Reset Responsibility

PM Managed

### Reset Location

Rock Island, Illinois - Joint Manufacturing and Technology Center

### Reset Cycle Time

150 Days

### - Contact Information -

877.4.PMSKOT (877.476.7568)  
[rock-pm-skot@conus.army.mil](mailto:rock-pm-skot@conus.army.mil)